OSHA CITATION TRACKING Total Violations 1st and 2nd Qtr FY 2008

Installation U.S. Navy - Puget Sound Naval Shipyard, 1400 Farragut Ave., Bremerton, WA 98314	UIC 61015	Open Conf. Inspection Date	Inspection Type Complaint	Violation Type Serious	Standard Cited 1910.303(b)(2)	Description Electrical, installation and use. Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling.	NAVOSH Reference OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	Abatement Date	Max Private Sector Penalty \$7,000
Naval Facilities Engineering Command, 400 Marshall Rd., Pearl Harbor, HI 96860	62813	1/7/2008	Planned	Serious	1910.22(d)(1)	Walking-working surfaces. In every building or other structure, or part thereof, used for mercantile, business, industrial, or storage purposes, the loads approved by the building official shall be marked on plates of approved design which shall be supplied and securely affixed by the owner of the building, or his duly authorized agent, in a conspicuous place in each space to which they relate. Such plates shall not be removed or defaced but, if lost, removed, or defaced, shall be replaced by the owner or his agent.	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	2/29/2008	\$7,000
Naval Facilities Engineering Command, 400 Marshall Rd., Pearl Harbor, HI 96860	62813	1/7/2008	Planned	Serious	1910.178(a)(4)	capacity and safe operation shall not be performed by the customer or user without manufacturers prior written approval. Capacity, operation, and maintenance	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	2/29/2008	\$7,000
Naval Base Point Loma, Bldg. 50, SUBASE, San Diego, CA 92106	63406	2/11/2008	Planned	Serious	1910.215(a)(1)	Machine guarding. Abrasive wheels shall be used only on machines provided with safety guards	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	3/14/2008	\$7,000

OSHA CITATION TRACKING Total Violations 1st and 2nd Qtr FY 2008

Naval Base Point Loma, Bldg. 50, SUBASE, San Diego, CA 92106	63406	2/11/2008	Planned	Serious	1910.215(a)(4)	construction and designed to be adjustable to compensate for wheel wear.	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	3/14/2008	\$7,000
Naval Base Point Loma, Bldg. 50, SUBASE, San Diego, CA 92106	63406	2/11/2008	Planned	Serious	1910.253(b)(4)(iii)	cylinders in storage shall be separated from fuel-gas cylinders or combustible materials (especially oil or grease), a minimum distance of 20 feet (6.1 m) or by	Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and	3/14/2008	\$7,000
Naval Base Point Loma, Bldg. 50, SUBASE, San Diego, CA 92106	63406	2/11/2008	Planned	Serious	1910.303(g)(1)(ii)	storage. When normally enclosed live parts are exposed for inspection or servicing, the working space, if in a	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	3/14/2008	\$7,000
Naval Base Point Loma, Bldg. 542, SUBASE, San Diego, CA 92106	63406	2/11/2008	Planned	Serious	1910.303(g)(1)(ii)	space about electric equipment. Working space may not be used for storage. When normally enclosed live parts are exposed for inspection or servicing, the working space, if in a	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	3/25/2008	\$7,000

OSHA CITATION TRACKING Total Violations

1st and 2nd Qtr FY 2008

Naval Base Point Loma, Recycling Center, Bldg. 379, San Diego, CA 92106		2/11/2008	Planned	Serious	1910.178(a)(4)	Powered Industrial trucks. Modifications and additions which affect capacity and safe operation shall not be performed by the customer or user without manufacturers prior written approval. Capacity, operation, and maintenance instruction plates, tags, or decals shall be changed accordingly.	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	3/28/2008	\$7,000
Naval Base Point Loma, Recycling Center, Bldg. 379, San Diego, CA 92106	63406	2/11/2008	Planned	Other	1910.178(a)(6)	Powered industrial trucks. The user shall see that all nameplates and markings are in place and are maintained in a legible condition.	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	3/28/2008	\$7,000
Naval Facilities Engineering Command, Sheet Metal Shop, Bldg. 429, San Diego, CA 92106	00245	3/6/2008	Planned	Serious	1910.106(d)(3)	constructed to limit the internal	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	4/7/2008	\$7,000
Naval Facilities Engineering Command, Sheet Metal Shop, Bldg. 429, San Diego, CA 92106	00245	3/6/2008	Planned	Other	1910.1200(g)(1)	Hazard Communication. Employers shall have a material safety data sheet in the workplace for each hazardous chemical which they use.	OPNAVINST 5100.23G Chapter 11, Inspections and Investigations of Workplaces by Federal and State OSH Officials; Chapter 5. Prevention and Control of Workplace Hazards	4/7/2008	\$7,000

OSHA CITATION TRACKING

Total Violations

1st and 2nd Qtr FY 2008

Naval Facilities	00245	3/6/2008	Planned	Serious	1910.303(g)(1)(ii)	Space about electric equipment.	OPNAVINST 5100.23G	4/2/2008	\$7,000
Engineering					(6)()()	Working space required by this standard	Chapter 11, Inspections		
Command, Wood						may not be used for storage. When	and Investigations of		
Shop, Bldg. 538,						normally enclosed live parts are exposed	Workplaces by Federal		
San Diego, CA						for inspection or servicing, the working	and State OSH Officials;		
92106						space, if in a passageway or general open	Chapter 5. Prevention and		
						space, shall be suitably guarded.	Control of Workplace		
						, , , , , , , , , , , , , , , , , , , ,	Hazards		
Fleet Readiness	00245	3/27/2008	Planned	Serious	1910.159c(8)(iii)	Fire protection. The employer shall	OPNAVINST 5100.23G	5/20/2008	\$7,000
Center SW, Bldg.					(// /	assure that sprinklers are protected from	Chapter 11, Inspections		
834, Paint Shop,						mechanical damage.	and Investigations of		
San Diego, CA							Workplaces by Federal		
92152							and State OSH Officials;		
							Chapter 5. Prevention and		
							Control of Workplace		
							Hazards		
Summary	Willful	Repeat	Serious	Other	Totals				
	0	0	12	2	14	1			
The abatement of	date is est	tablished by	the OSHA a	rea office.	The period of time	ne to abate a hazard is the shortest	interval that an employ	er	
can reasonably be expected to correct the violation.									
The OSHA Act a	uthorizes	civil penalt	ies be asses:	sed for eac	ch alleged violation	on. Most Federal agencies are exem	pt from these fines.		
Penalties are	based o	n four facto	rs: 1) the gra	vity of the	violation; 2) the s	size of the business; 3) the good fait	th of the employer, and		
4) the employer's history of previous violations.									